

1 Causes of defects associated with tolerances in construction: A case study

2 Saeed Talebi¹, Lauri Koskela², Patricia Tzortzopoulos³, Michail Kagioglou⁴,

3 Chris Rausch⁵, Faris Elghaish⁶, Mani Poshdar⁷

4 ¹Senior Lecturer, School of Engineering and the Built Environment, Birmingham City
5 University, Birmingham, UK, B4 7AP (corresponding author); Saeed.Talebi@bcu.ac.uk

6 ²Professor, Innovative Design Lab, School of Art, Design and Architecture, University of
7 Huddersfield, Huddersfield, UK, HD1 3DH; L.Koskela@hud.ac.uk

8 ³Professor, Innovative Design Lab, School of Art, Design and Architecture, University of
9 Huddersfield, Huddersfield, UK, HD1 3DH; P.Tzortzopoulos@hud.ac.uk

10 ⁴Professor, School of Engineering, Western Sydney University, Sydney, Australia,
11 NSW 2751; M.Kagioglou@westernsydney.edu.au

12 ⁵Ph.D. Candidate, Department of Civil and Environmental Engineering, University of
13 Waterloo, Waterloo, ON, Canada, N2L 3G1; Chris.Rausch@uwaterloo.ca

14 ⁶Teaching Fellow, University of Portsmouth, School of Civil Engineering and Surveying,
15 Portsmouth, UK, PO12UP; faris.elghaish@port.ac.uk

16 ⁷Senior Lecturer, Department of Built Environment Engineering, Auckland University of
17 Technology, Auckland, New Zealand, 92019; mani.poshdar@aut.ac.nz

18 Abstract

19 Defects associated with dimensional and geometric variations (tolerance issues) are amongst
20 the most costly and recurring defects in construction projects, yet the identification and
21 mitigation of the causes of tolerance issues appear to be lacking in the construction industry.
22 To enable the development of widely acceptable solutions for the perennial challenge of

23 tolerance management, a more in-depth understanding of causes of tolerance issues should be
24 established. The aim of the research presented in this paper is to identify the potential causes
25 of tolerance issues in construction based on a literature review and empirical studies. This
26 research uses a case study approach. The empirical data is collected through direct
27 observations, group interviews, semi-structured interviews and document reviews. Having
28 triangulated the findings, a list of eighteen potential causes were derived for the eleven
29 observed tolerance issues in two case study projects. The contribution of this paper to
30 knowledge in engineering management is fourfold: (1) the limitations of prior studies on causes
31 of tolerance issues are revealed, (2) the empirical studies led to not only verifying and refining
32 the causes collected from the literature by considering them in the context of the identified
33 tolerance issues, but also finding new causes in the context of tolerance management when
34 compared to literature, (3) the identified causes provide insight into reasons behind the
35 recurrence of tolerance issues across the industry, and (4) it investigates the causes of tolerance
36 issues while balancing managerial and engineering views. The findings of this study provide
37 a pivotal basis for construction practitioners to develop effective solutions for tolerance
38 management whereby tolerance risks can be identified and mitigated in a prescient manner,
39 which can result in a significant amount of savings.

40 **Keywords:** Tolerance issues, tolerance management, quality control, defects, dimensional
41 and geometric variations.

42 **Introduction**

43 Defects associated with tolerances, called tolerance issues hereafter, are amongst the most
44 common and recurring defects in construction projects (Landin 2010; Talebi et al. 2020a).
45 Tolerances issues (e.g. lack of fit, misalignment between components, aesthetically

46 unacceptable gaps) can adversely impact structural safety, constructability, aesthetic,
47 functionality, and can lead to delays, cost overruns and material wastage (Rausch et al. 2019).

48 Over the last two decades, several authors have tried to develop ways of mitigating tolerance
49 issues (i.e. solutions for tolerance management) (e.g. Milberg 2006; Talebi 2019) whereby
50 designers and practitioners can gain proactive insight into avoiding tolerance issues. However,
51 the construction industry is yet to find a widely accepted solution for tolerance management
52 (Enshassi et al. 2020; Seymour et al. 1997). As a result, tolerance issues are often mitigated at
53 the time and place of the construction process reactively with intensive rework (Milberg and
54 Tommelein 2009; Savoini and Lafhaj 2017).

55 Liker (2004) states that solving a problem by finding suitable and workable solutions first
56 requires the identification of its causes. More specifically, designing a solution to move from
57 being reactive to proactive in managing tolerances requires the identification and elimination
58 of causes of tolerance issues (Meiling et al. 2014). However, as far as it is known, very little
59 literature exists with the main focus on thoroughly collating causes of these specific types of
60 defects. The definition of tolerance issues and their causes remain vague as the existing
61 literature either merely presents the authors' (e.g. Talebi et al. 2016) or participants'
62 perceptions (e.g. Jingmond et al. 2011) rather than finding causes through rich empirical data
63 (Forsythe 2006; Rausch et al. 2020). As such, there is a need for a study based on empirical
64 data to thoroughly identify causes of tolerance issues prior to any attempt to develop a solution
65 for tolerance management.

66 The aim of the research reported in this paper is to present potential causes of tolerance
67 issues in construction. The paper is structured as follows. First, the causes of tolerance issues
68 from the literature are discussed. The research method adopted to collate and analyse data is
69 addressed. The causes of tolerance issues identified during the empirical studies are presented.

70 The findings and contributions to knowledge are discussed. Finally, conclusions drawn from
71 the research and areas for further research are presented.

72 **Causes of tolerance issues in construction**

73 It is important to first investigate causes of tolerance issues in the literature. Berg and
74 Holicky (1989) state that ambiguous communication of tolerance requirements, insufficient
75 tolerance information in specifications, and negligence of tolerances during the tender process
76 are some of the causes of tolerance issues. Seymour et al. (1997) add two more causes: (1) poor
77 workmanship, and (2) an over-reliance on unsuitable tolerances in reference documents. Poor
78 workmanship can be due to the inaccuracy of the execution of work on site (e.g. when erecting
79 prefabricated walls) and inaccuracy of equipment used for installation (Jingmond et al. 2011).
80 Milberg (2006) argues that (1) incomplete or missing tolerance information in specifications,
81 which results in multiple interpretations of tolerance requirements by contractors and
82 inspectors, (2) incompatibility between the specified tolerances and process capabilities, and
83 (3) poor datum selection, being the main causes. Process capability in the context of tolerance
84 management, is defined as “the likelihood that a process...will result in an outcome that meets
85 a given tolerance specification. It may be represented by a probability distribution to describe
86 the variation in the geometry of the material output of a process under normal operating
87 conditions” (Tommelein and Ballard 2018). A datum is a theoretically exact geometry from
88 which the geometric or location characteristics of a feature are established (Sun and Gao 2018).
89 The latter two causes show that tolerance management in construction has its roots in the
90 manufacturing industry.

91 Jingmond and Ågren (2015) adopt an approach based on the use of cognitive mapping and
92 the notion of process causality in order to identify causes of defects in construction. They
93 believe that causes of defects associated with tolerances are due to the unforeseen behaviour of

94 materials and the inaccuracy of measuring devices. Regarding the latter cause, measuring
95 devices range from moderately accurate (e.g. measuring tapes) to extremely accurate (e.g.
96 automated electronic devices) (Chen et al. 2020). The inaccuracy of measurement devices may
97 be considerable relative to allowable deviations of structures and components that are
98 connected to the structures. Conventional instruments heavily rely on sampling techniques,
99 which makes the results prone to the risk of being inaccurate (Arashpour et al. 2020; Phares et
100 al. 2004). The challenge with the application of recently developed measurement instruments
101 (e.g. terrestrial laser scanner) is their high cost (Puri et al. 2018) and a lack of adequate research
102 on how to best utilize their level of accuracy (Rebolj et al. 2017). This is especially important
103 in the context of tolerance management since the allocation of a specific level of accuracy from
104 a measurement device needs to mitigate risk in a cost-optimal manner.

105 The construction industry is currently in a transitional state. It is neither completely craft-
106 based, nor fully industrialised (Kagioglou et al. 2001). Hence, it is essential to establish
107 reference documents and to understand what normal (or expected) tolerances are (Price et al.
108 2019). However, there are still many construction tolerances that are not covered in industry
109 standards (Ballast 2007; Jingmond and Ågren 2015), and the existing standard tolerances may
110 be either unreasonably “tight” or “loose” (Milberg and Tommelein 2019; Talebi et al. 2016).
111 Holbek and Anderson (1977) state that although tolerances in the construction industry have
112 been developed for materials, such as steel and concrete, there is little input on the issue of
113 conflicting tolerances at the interfaces between different materials and components. Many
114 years later, the industry still struggles with the same challenge and the subject of interfacing
115 between components is yet to be resolved (Enshassi et al. 2020).

116 The verification of the compliance with tolerance requirements on site is performed
117 according to the reference documents listed in specifications provided by the designers (Frank
118 2012). Shammass-Toma et al. (1996) argue that this is an ineffective quality control process and

119 should be replaced by quality control documents in which achievable tolerance values based
120 on project conditions can be found. However, quality control documents often do not include
121 adequate tolerance information (Shammas-Toma et al. 1996).

122 All building components are subject to such variation in their size, form, orientation and
123 position, which cannot be precisely determined at the design stage (Davison and Owens 2012;
124 Rahman 2014; Vorlíček and Holický 1989). In the case of mixed-material building systems
125 (e.g. hybrid steel, concrete, timber, etc.), there is a greater systemic interaction of material
126 types, which can give way to more tolerance issues (Alexander 2014; Lawson et al. 2014). The
127 building process itself adds more inevitable geometric variations to components because loads
128 being applied to the building structure gradually increase during the construction process, and
129 this leads to more building movement (Landin and Kämpe 2007). Variations are accumulated
130 through components and assemblies, possibly resulting in the lack of fit or malfunction of
131 assemblies (Abdul Nabi and El-adaway 2020; Shahtaheri et al. 2017). Designers must not only
132 account for the impact of variation sources individually, but also the impact of variations when
133 combined with the dimensional and geometric characteristics of components and assemblies
134 (Talebi et al. 2019). However, the industry lacks accurate and validated guidance to quantify
135 expected movements (Alexander 2014) and designers frequently ignore the accumulation
136 effects of combined deviations (Ballast 2007; Milberg 2006; Milberg and Tommelein 2019;
137 Rausch et al. 2019; Rausch et al. 2017; Safapour and Kermanshachi 2019).

138 During construction, building structures are not protected but are exposed to environmental
139 conditions; particularly changes of temperature, rain, snow and humidity, sometimes for a long
140 time. Such environmental conditions may lead to changes in form and size of components after
141 they are constructed and subsequently result in tolerance issues (Alexander 2014). This is
142 evidently seen in bridge construction and in large buildings where expansion joints are
143 necessary for ensuring that a structure is not over-constrained due to thermal changes. Changes

144 in temperature, including temperature difference across a component or changes in the average
145 temperature of an assembly, are a source of building movement, especially in steel structures.
146 Rain and snow can directly damage the accuracy of the final work (e.g. flatness of fresh
147 concrete on metal decking in composite construction) (Alexander and Lawson 1981) or can
148 result in ponding. Ponding occurs when water collects on a surface (e.g. roof) to a sufficient
149 depth, causing deflection. Also, according to (ACI 2014), when concrete is poured, humidity
150 can significantly affect the amount of drying shrinkage, which can lead to deflection in beams
151 and slabs if not properly managed.

152 Other causes of tolerance issues found in the literature include the lack of tolerance
153 coordination between design disciplines and construction trades (ACI 2014; Jingmond and
154 Ågren 2015), the lack of terminology to communicate tolerance information (i.e. characteristic
155 of tolerances and tolerance values) (Alshawi and Underwood 1996; Ballast 2007; Berg and
156 Holicky 1989; Jingmond and Ågren 2015; Milberg 2006; Talebi et al. 2020a; Talebi et al.
157 2020b), poor product design (e.g. the lack of the provision of appropriate connections to absorb
158 deviations) (ACI 2014; Milberg and Tommelein 2019), unforeseen special causes (e.g. tool
159 breakdown) (ACI 2014).

160 Table 1 summarises the identified causes of tolerance issues in the literature and indicates
161 the authors discussing each cause. The review of the literature shows that prior studies
162 concerning the causes of tolerance issues are restricted due to one or more of the following
163 reasons in addition to not being based on empirical data: (a) they do not investigate the causes
164 of tolerance problems in a broad construction setting, from project management to engineering
165 and from design to construction; however, investigating causes of tolerance issues would
166 require an amalgamation of different disciplines (Talebi 2019), and (b) they mainly focus on a
167 few causes of tolerance issues and a unified list of causes for tolerance issues is missing. All in
168 all, according to Landin (2010) and Jingmond and Ågren (2015), the extant research tends to

169 discuss causes in a somewhat superficial manner by placing the responsibility with designers,
170 operatives, and quality systems. For these reasons, tolerance defects continue to emerge within
171 projects and create challenging barriers to overcome.

172

173 **Table 1.** List of causes related to tolerance defects identified in the literature.

174 **Research Method**

175 This research adopts a case study approach. Such an approach is suitable when describing,
176 explaining, and exploring a contemporary phenomenon, and gaining an in-depth understanding
177 of real-world events (Yin 2013). In other words, the purpose of the case study is not to simply
178 describe the events within a real-world context but rather to investigate underlying reasons as
179 to why and how those events actually occur (Eisenhardt 1989). The case study approach is
180 suitable for this research because it aims to thoroughly investigate why and how tolerance
181 issues occur.

182 Although surveys are a common research method to identify the causes of defects (Knight
183 and Ruddock 2009), using them do not necessarily invoke new understanding or in-depth
184 verification of the causes identified in existing literature (Rosenfeld 2013; Ye et al. 2015).
185 According to Robson and McCartan (2015), understanding why a real-world problem occurs
186 requires asking those involved in practice. The case study approach in this research facilitates
187 the collection of data in the context for which tolerance issues are experienced. The data is
188 collected in the two case projects through direct observations on site, two group interviews,
189 sixteen semi-structured interviews and document reviews.

190 **Rationale for case selection**

191 No widely accepted strategy exists for the selection of right cases beyond the advice to select
192 cases which are ‘most likely’ to address the research aim (Brinkmann 2013). Accordingly,

193 purposive sampling was adopted for the selection of cases and participants in the interviews.
194 The purposive sampling highlights the importance of conscious decision-making and is used
195 when dealing with a small sample and particularly when informative samples are meant to be
196 selected (Saunders et al. 2016). The following criteria were considered for the selection of
197 cases: (1) the acknowledgement of the need to develop a solution for tolerance management
198 whereby tolerance issues can be managed proactively, (2) provision of access to construction
199 sites and documents, and (3) the stage of development of the project. Regarding the latter
200 criterion, only those projects where the connection between the structural frame and other
201 components had not been constructed yet were considered since tolerance issues frequently
202 occur in such connections (Talebi et al. 2020a). Eleven of the pre-identified tolerance issues
203 were also identified during the empirical studies, that is, the selected cases were informative
204 and the purposive sampling in this study ensured that appropriate cases have been selected.
205 Details of the case projects and their development stages can be found in Table 2.

206 **Table 2.** Details of case projects and their stage of development.

207 **Data collection and analysis**

208 The direct (non-participant) observation (O'Leary 2004) was carried out on sites of both
209 projects. The observation period in project A was 10 months and it lasted 5 months in project
210 B. There were seven tolerance issues in A and four tolerance issues in B. The observations
211 stemming from A included the installation of curtainwalls, the partitioning, the fins
212 (architectural features that were attached to the building envelope for aesthetic purposes) and
213 the cladding. The observations from B covered the erection of the steelwork and the installation
214 of cladding and doors. The identified tolerance issues are presented in Table 3.

215 **Table 3.** Details of the tolerance issues identified in projects A and B.

216 Two group interviews were then conducted to validate and refine the description of the
217 tolerance issues. The details of the participants in each group interview are given in Table 4.

218 The managing directors of the general contractors in projects A and B suggested interviewees
219 based on the following criteria: (1) all of them had more than 10 years of experience in dealing
220 with tolerance issues, (2) they were involved in the project from the beginning, and (3) were
221 fully aware of the identified tolerance issues in each project. This ensured that purposive
222 sampling had been followed carefully and the right participants had been invited to those group
223 interviews, which is more important than the number of participants (Brinkmann 2013).

224 **Table 4.** Role and position of interviewees in projects A and B.

225 Sixteen semi-structured interviews were conducted with the same group of interviewees
226 who were involved in the group interviews in order to capture opinions of the industry
227 practitioners (Brinkmann 2013) concerning the causes of tolerance issues. The semi-structured
228 interviews were conducted in 2016 and 2017. Having experts with different backgrounds helps
229 to obtain a balanced view of the research topic and avoid subjectivity from a particular role's
230 viewpoint (Saunders et al. 2016).

231 Of note is that the literature review in this research was carried out in two stages. The first
232 stage was completed before starting the semi-structured interviews in 2016, and led to a list of
233 causes of tolerance issues. The list was sent to the participants of face-to-face interviews for
234 their reference. In particular, the participants were asked to consider unique characteristics of
235 tolerance issues identified in their own project. The second stage of literature review continued,
236 and it covered the most recent and pertinent literature. However, as can be seen from Table 1,
237 no new causes were identified from publications since 2016. In other words, if the authors were
238 to conduct the interviews again today, the same list of causes would be sent to the interviewees
239 as the one sent in 2016. The second stage of literature review was to augment the first stage
240 and make the research relevant to today's body of knowledge, and subsequently, to enable the
241 authors perform more informed analysis on the collected data.

242 Interviews were conducted face-to-face and they took between 30 and 50 minutes. After
243 completing the interviews, transcriptions from the recorded interviews were generated at this
244 stage. Verbatim comments are included in quotations in this paper to communicate the ‘lived
245 experience’ of the practitioners undertaking the work.

246 Document reviews were then used to corroborate evidence collected from interviews and to
247 verify information given by interviewees through cross-checking transcriptions with the
248 information in the reviewed documents. The review of documents review led to increased
249 credibility and internal validity of this research (Taylor et al. 2015). Data collected from
250 document reviews is indicated in the findings section. Documents used to disseminate tolerance
251 information (i.e. specifications) were reviewed at this stage.

252 Content analysis was applied to interview transcripts for identifying the causes of tolerance
253 issues. Other methods exist to analyse causes of defects such as cognitive mapping (CM),
254 causal loop diagram (CLD) and Fishbone diagram (FD). The use of qualitative diagrammatic
255 aids such DM, CLD and FB are based on heuristic rules (Love, Edwards, & Smith, 2016). Love
256 et al. (2016) contend that the use of such heuristic rules may contribute to the stagnation in
257 research on causation, and subsequently, impair improvements in practice. The deployment of
258 content analysis in this research was to recognise the foremost facets of a data set by thoroughly
259 interpreting the interview transcripts rather than simply counting the number of times a topic
260 is raised or presenting direct responses about what the causes are (Fellows and Liu 2015). The
261 content analysis deployed presents information extracted from interviewees that address ‘why’
262 and ‘how’ tolerance issues in each project occurred. A summary of findings is presented in the
263 next section. Quotations from interviews are improved for readability and it is indicated where
264 the data collated from interviews and document review is used. Consolidating the findings from
265 the literature and interviews resulted in the identification of eighteen causes of the tolerance
266 issues.

267 **Findings: Causes of Tolerance issues**

268 **Causes of Tolerance Issue 1**

269 According to the project brief developed by the client, “a decorative polished concrete floor
270 system should be used in the Atria Space, Social Space and Circulation Spaces”. However,
271 the project brief does not specify the exact flatness tolerance or construction method to
272 achieve highly flat concrete slabs (Interviewee 1). The general contractor, who was
273 responsible for design and construction in project A, decided to use the composite steel deck
274 floors because this construction method is normally cheaper than other flooring methods and
275 enables quicker pouring of concrete (Interviewees 1, 3, 4, 5, 6). Using a cheaper work method
276 made the general contractor more competitive when bidding for the project (Interviewees 1,
277 5, 6). If the project budget had been higher, the general contractor could have used other
278 alternatives for the floors (Interviewees 3, 6) such as pre-cast planks (Interviewees 1, 4, 6). In
279 that case, slabs would have had less deflection and “likely the tighter flatness tolerances when
280 concrete is the final finish could have been achieved” (Interviewee 3). Given the challenge
281 with the excessive deflections when using the composite steel deck floors, the mitigation
282 strategy to fix the unacceptable deviations in flatness of concrete slabs was to use a concrete
283 floor levelling compound to achieve the required flatness tolerance (Interviewees 5, 7). In
284 other words, interviewees infer that due to the *inconsistency between the tolerance*
285 *requirements of the project and its budget*, the contractor had to select an *inferior type of*
286 *construction method* (Interviewees 1, 3, 4, 5, 6), which led to not achieving the flatness
287 tolerance requirement. As a result, the recessed skirting and door frames were either
288 conflicted with the concrete slab or there was a gap between the them and the slabs (see
289 Figure 1). In (BSI 1994), it is stated that if the soffit deflection is considered important, the
290 permitted deflection tolerance should be reduced. However, the designer only relied on the
291 given tolerance values in the reference document and did not assign tighter tolerances to

292 control flatness (i.e. *overreliance on reference documents*) (Interviewee 1, 2, 3). Moreover,
293 although the project brief asks for a decorative polished concrete floor system, it does not
294 specify the structural system required to have the polished concrete as the final finish. As a
295 result, the general contractor decided to put the price based on an inappropriate working
296 method for this purpose and then call upon contingency fund for remedial actions to achieve
297 the requirements after being awarded the project (i.e. *an incomplete project brief given by*
298 *the client*) (Interviewees 1, 2, 3, 4). The Interviewee 7 pointed out that raining exacerbated
299 the situation with the flatness of slabs (i.e. *environmental condition*).

300 **Fig. 1.** Excessive gap between the skirting and the concrete slab.

301 **Cause of Tolerance Issue 2**

302 The concrete subcontractor had to stop working in the evenings when pouring upper floors
303 due to complaints from residents living around the site to the Environment Agency of the
304 Local Authority and could not use the power float when it started to rain (Interviewees 1, 7).
305 Rain as an *environmental condition* (Interviews 6, 8) and people's complaints as an
306 *unforeseen special cause* (Interviewees 2, 8) "made it difficult for the concrete subcontractor
307 to achieve the required [flatness tolerances in] surfaces" (Interviewee 8) (Figure 2).

308 **Fig. 2.** Flatness of concrete slabs affected by special issues.

309 **Causes of Tolerance Issue 3**

310 According to the concrete specification, "the general contractor is responsible for obtaining
311 the positions and sizes of all holes, brackets etc., from all subcontractors and should
312 accurately set out and form them". However, due to the *poor communication* between the
313 general contractor, cladding subcontractor and concrete subcontractor, "the position of the
314 brackets and permissible deviation in the position of the slab edge was not coordinated"
315 (Interviewee 4). The Interviewees 2 and 7 state that none of the specifications and reference
316 documents considered conflicting tolerances in interfaces between the concrete elements,

317 steel elements, and cladding system and they only revolved around tolerances of one
318 component. Hence, “the clash between the cladding bracket and concrete slabs when the
319 concrete slabs are protruding the target surface had not been detected” (i.e. *Insufficient*
320 *tolerance information in specifications, the lack of tolerances for interfacing components*
321 *in reference documents*) (Interviewee 7). CONSTRUCT Concrete Structure Group (2010)
322 states that the permitted deviation for the position of the slab edge relative to the actual
323 position of the slab edge is ± 10 mm. However, “as soon as the concrete slabs at the roof level
324 start to deviate towards outside the building, they will conflict with the cladding brackets”
325 (Interviewee 7), which shows the *over-reliance on reference documents to specify*
326 *tolerances* resulting in this tolerance issue. Given that the concrete edge protruded more than
327 permitted from the surface of the steel beam, the bracket could not be installed without
328 cutting the edge of the slab (Interviewees 1, 8, 9) (Figure 3).

329 **Fig. 3.** Modified edge of the concrete slab.

330 **Causes of Tolerance Issue 4**

331 The Steel Framing Systems (SFS) studs were out of plumb (Figure 4). “None of the Quality
332 Check Sheets included information about the permissible deviations of the plumbness of the
333 SFS studs” (Interviewee 1), or “how and when they should be measured” (Interviewee 1). As
334 a result, the tolerance problem with the SFS studs was recognised after they were handed
335 over by the cladding subcontractor (Interviewee 7), when “they started to build their system
336 on the SFS studs” (Interviewee 7). Thus, this problem was due to *ineffective quality control*
337 *documents*. Also, Interviewee 4 says that given “the operatives had to complete their work as
338 quickly as possible, they were not that much concerned about the quality of their work”.
339 Hence, *poor workmanship* was another cause behind this tolerance issue.

340 **Causes of Tolerance Issue 5**

341 The cladding subcontractor developed a design in which the offset from the steelwork to the
342 face of the stone panels was 272 mm. In this case, the cladding system could absorb 32 mm
343 of deviations due to the inclination of steel columns and stone panels. The Architect later
344 increased the offset to 290 mm (Interviewees 1, 2, 6, 8) (Figure 4). This was to accommodate
345 the installation between the steelwork and cladding. “There was *miscommunication* between
346 the architect and the cladding subcontractor about the required distance from the steel to the
347 face of the stone panels” (Interviewee 2). The subcontractor’s input was delayed
348 (Interviewees 1), and “the architect was not convinced to change the design” (Interviewee 1)
349 as “the connection type between the steelwork and cladding system had been designed”
350 (Interviewee 5). Later during construction, “the architect, structural engineer, steel
351 subcontractor and cladding contractor could not conclude how deviations of the steelwork
352 would impact the geometric accuracy of the steelwork and the cladding system” (Interviewee
353 6) due to poor tolerance communication. As a result, the cladding system was not capable of
354 accommodating the deviations (Interviewees 9). Indeed, the steel frame, “was not stiff
355 enough due to the poor structural design” (Interviewee 9) and columns in the Elevation 4
356 were leaning into the building more than it was anticipated (i.e. *unforeseen behaviour of*
357 *materials and the lack of accurate guidance to anticipate the exact building movements*)
358 (Interviewees 1, 6, 7, 9).

359 **Fig. 4.** Excessive perpendicularity variations of columns and stone panels.

360 **Causes of Tolerance Issue 6**

361 When the cladding subcontractor put the stone panels on and the dead load was applied to the
362 steel frame, the stone panels started to sag. This meant that the cladding did not stay at the
363 correct level and, in general, everything was sinking downwards. It was noticeable that the
364 gap between the channel and the stone panel in some areas were bigger and the gap was not
365 consistent all the way through (Figure 5). There was *miscommunication* between the

366 steelwork contractor, cladding contractor, and the general contractor did not perceive the
367 importance of having movement joints, thus, denied to have it (Interviewees 1, 7, 8, 9). In the
368 specification for the cladding system prepared by a consultant, it was stated that “movement
369 joints are not required”. However, it turned out that this *tolerance-related information in the*
370 *specification was inaccurate*. The Interviewees 1 and 9 believed that using movement joints
371 had been neglected because such joints would have been costly and exceeded the allocated
372 budget for the cladding (i.e. *inconsistency between tolerance requirements of the project*
373 *and its budget*). Eventually, this tolerance issue occurred due to *the exceeding deflection and*
374 *twist of beams more than anticipated* (Interviewees 7, 8, 9).

375 **Fig. 5.** Inconsistent gaps in some areas between the channel and the stone panel.

376 **Causes of Tolerance Issue 7**

377 According to the Interviewees 1, 2 and 9, no specification had been developed into a unified
378 document to consider tolerances of the fins and steel structure but rather tolerance
379 information for each component could be found in dispersed specifications (i.e. *fragmented*
380 *tolerance information in specifications*). In the specification called ‘projecting feature fin
381 system’, it is stated that any points on the steel columns are allowed to have the tolerance of
382 ± 10 mm. It turned out this tolerance was not achievable by the steel subcontractor
383 (Interviewees 2 and 8). This indicates not only *inaccurate tolerance information in*
384 *specifications* (Interviewees 1, 2, 8, 9) but also *incompatibility between the specified*
385 *tolerances and process capability* (Interviewees 1, 8) (Figure 6). Hence, the design of
386 connections between the steelwork and fins had to change to accommodate more deviations
387 (Interviewee 1, 6, 7, 9) as columns on level 3 were more than 30 mm out of plumbness (i.e.
388 *inferior design of connections*) (Interviewees 7, 9).

389 **Fig. 6.** Connection between the structural frame and a fin and the specified tolerances for the
390 steel columns

391 **Causes of Tolerance Issue 8**

392 No information could be found in the specifications indicating that parallelism of stanchions
393 is essential to ensure that the electrically operated shutter doors will fit in the doorways (i.e.
394 *insufficient tolerance information in specifications*) (Interviewees 10, 14). “There was *no*
395 *communication of tolerance information* before construction whatsoever” (Interviewee 11).
396 The only information communicated between the site manager and the steel subcontractor
397 was whether deviations in the plumbness of installed columns and in the position of the
398 installed base plates complied with the tolerances stated in BCSA (British Constructional
399 Steelwork Association) (2010) (Interviewees 11, 12). As a result, despite the fact that the
400 steel and cladding subcontractors were functioning in the project as one entity, the required
401 tolerance for the steel work to fit the shutter doors was not communicated between them
402 (Interviewees 10, 12, 14). Moreover, the structural designer had tried to use steel and
403 ancillaries as little as possible (Interviewee 13). The two sides of the doorways were “neither
404 connected to each other nor [were] they ... fixed to the ground” (Interviewee 11), that is, they
405 are free standing. The *inconsistency between a tolerance requirement* (i.e. fitting the shutter
406 door without any rework) *and its budget* led to a situation that by aligning one side of a
407 cladding rail, the other side was becoming out of alignment (Interviewees 10-12) (Figure 7).
408 This inconsistency was to cut down the project costs but resulted in a tolerance issue
409 (Interviewee 14). “Setting a datum to either side of the doorway could have helped the people
410 on site to install the columns right in the first try” (Interviewee 11). This could also have
411 assisted the site engineer to align the columns easier (Interviewees 11) (i.e. *poor datum*
412 *selection*). The Interviewee 15 believed that this tolerance issue shows that practitioners do

413 not often have adequate knowledge about tolerances (i.e. *lack of training on tolerance*
414 *management*).

415 **Fig. 7.** Misalignment of stanchions.

416 **Causes of Tolerance Issue 9**

417 The purlins on the roof, which support the cladding panels, were neither straight nor in their
418 correct positions (Interviewees 13, 16) (Figure 8). As a result, there were no fixing points for
419 the panels (Interviewee 13). A document, ‘Method of Erection’, issued by the steel
420 subcontractor, states that “the feature steelwork and stringers are to be co-ordinated into the
421 structure as the work progresses”. This implies that tolerances of the purlins and panels had to
422 be coordinated to accommodate deviations in their joints. However, there is not any hint in
423 this document about how to install the purlins and avoid the risk of having them be wavy (i.e.
424 *insufficient information in specifications*) (Interviewee 13). Moreover, *poor workmanship*
425 is another cause of the issue with the purlins (Interviewees 10-12, 14, 15). If the steel
426 subcontractor had been competent, they would have assessed whether the cladding
427 subcontractor could be able to install the roof panels between the purlins (Interviewee 13).

428 **Fig. 8.** Wavy purlins on the roof.

429 **Causes of Tolerance Issue 10**

430 The building was erected from two sides: the first erected side initiated from Gridline 1 and
431 continued to Gridline 30 and the second erected side started from Gridline 31 and was
432 connected to Gridline 30. Hence, there was an interface between these two sides of the
433 structure in Gridline 30. The columns in Gridlines 31 were out of plumb and they were
434 leaning towards the inside of the building. Also, the entire columns in the first erected side of
435 the structure were oriented towards the first erected side. As a result, the beam coming across

436 the top between Gridlines 28E and 30E from the initial side overlapped Gridline 30E where it
437 connects two sides of the building (Figure 9).

438 The decision of erecting the steelwork in two pieces was wrong from the tolerance point of
439 view (Interviewees 10, 14), especially without considering any solution to make the
440 deviations of both sides more compatible to each other (Interviewee 14) (i.e. *inferior types of*
441 *construction methods*). The Interviewee 14 believed that the accumulation of deviations
442 when installing base plates and columns had been disregarded (i.e. *neglecting the*
443 *accumulation effects of deviations*). As part of the contract with the steel subcontractor, the
444 general contractor could have asked for an engineer to monitor the steel erection on site
445 continuously. This would somewhat yield to an additional cost for the general contractor
446 (Interviewees 10, 12). Not having an internal site engineer due to *inconsistency between the*
447 *required accuracy and the project's budget* resulted in a steelwork which is considerably out
448 of tolerance, the lack fit on the roof, and a relatively high amount of rework (Interviewees 10,
449 12). Interviewee 13 added that even “if the steel subcontractor was more conscious about
450 tolerances, the second erected side would have been erected as accurate as possible”.
451 However, “the second erected side had the worst deviations compared to the first side of the
452 structure” (Interviewee 11). Interviewee 11 implied that the out of tolerance steelwork
453 particularly in the second erected side was due to *poor workmanship*.

454 **Fig. 9.** Lack of fit of the beam between two gridlines.

455 **Cause of Tolerance Issue 11**

456 The frames for personnel doors were neither plumb nor square. The personnel doors were
457 ‘squeezed’ too tight, resulting in a non-square condition, and they could not be shut and
458 opened properly. According to the Interviewees 13 and 15, the cladding subcontractor had
459 measured the distance between the posts making the doorframes at the bottom and top using a

460 conventional measuring tape. However, “they ignored the fact that the doorframes actually
461 can be oriented either to left or right side even though when those distances are the same”
462 (Interviewee 14) and a measuring tape is an *inappropriate measurement instrument* to check
463 the plumbness tolerance of the doorframes (Interviewees 11, 13).

464 **Discussion**

465 The literature review in this study revealed the limitations of prior studies focusing on the
466 causes of tolerance issues. The knowledge of these restrictions was gained after a thorough
467 literature review and should be considered as a contribution to theory. These restrictions have
468 made the causes of tolerance issues obscure and therefore, an in-depth study in this field is
469 needed prior to any attempt to develop a solution for tolerance management. To tackle the
470 existing shortcomings, the case study approach was adopted and a substantial amount of
471 empirical studies were carried out, causes of tolerance issues were investigated from both the
472 managerial and engineering aspects, and a list of causes based on the findings from the
473 literature and empirical studies was generated.

474 Eleven tolerance issues were identified during observations in case projects A and B, and
475 they were validated during two group interviews. The causes of these tolerance issues were
476 then explored during sixteen semi-structured interviews with practitioners who frequently deal
477 with such issues. Given that the definition of tolerance issues is still vague in the literature and
478 that most of the existing literature is based on subjective views, this research contributes to the
479 existing theory by providing a better understanding of the characteristics of tangible tolerance
480 issues in practice and their causes.

481 The findings from the observations and interviews helped to verify and refine the causes
482 collected from the literature by bringing them in the context of the identified tolerance issues,
483 and also to find causes that had not been considered in the tolerance management body of

484 knowledge. ‘Insufficient tolerance information in specifications’ is a cause for tolerance issues
485 identified in the literature. This cause was refined further during this study as it was
486 demonstrated that inaccurate and fragmented tolerance information in specifications led to
487 tolerance issues 6 and 7. Accordingly, it was suggested that the ‘insufficient, inaccurate and
488 fragmented tolerance information in specifications’ is the correct cause (Interviewees 1, 2, 4,
489 7, 8, 9). ‘Lack of tolerance coordination during the project’ was found in the literature,
490 however, all the interviewees believed that it is a subset of ‘poor communication of tolerance
491 information’ and should be eliminated from the list as an independent cause. ‘Negligence of
492 tolerances during the tender process’ appears to be another cause identified in the literature.
493 However, the findings from the interviews show that ‘an incomplete project brief’ is one of the
494 reasons that leads to such negligence and should be considered as the actual cause for tolerance
495 issues (Interviewees 1-4, 8, 10, 13). In addition, this research verified three causes that have
496 been identified in settings outside the context of tolerance management, and it demonstrated
497 that they should be equally considered as causes of tolerance issues. Those causes are
498 ‘inconsistency between tolerance requirements of the project and its budget’, ‘an incomplete
499 project brief’, and ‘inferior types of construction methods’. Refining and verifying the causes
500 as well as finding causes that had not been identified in the tolerance management literature
501 are contributions to knowledge from this research.

502 ‘Unforeseen special causes’ and ‘lack of training on tolerance management’ were found in
503 both the literature and empirical studies. Deming (2000) speculates that the majority of the
504 causes of problems stem from the system (of production) and only a few of them are due to
505 special causes, emanating from fleeting events (Deming 2000). In line with this statement, most
506 of the identified tolerance issues in this study occurred due to causes stemming from the system
507 (of production), and the ‘special cause’ as such was only recognised in the tolerance issue 2.
508 Moreover, ‘lack of training on tolerance management’ was found only for the tolerance issue

509 8. Nevertheless, insufficient training is known to be often inherent in the occurrence of all
510 tolerance issues (Milberg and Tommelein 2019; Talebi et al. 2016). Given that tolerance issues
511 are amongst the most recurring defects, with potentially severe consequences, the subject of
512 tolerance management should be included in the curricula for the designers and contractors
513 (Milberg and Tommelein 2019).

514 Table 5 shows the refined list of the identified causes through the literature review and
515 empirical studies, and in which tolerance issue (TI) those causes have been found.

516 **Table 5.** List of the causes found in the literature and empirical studies

517 There has been little quantitative analysis of the magnitude, cost, and consequences of
518 tolerance issues. Brookes (2005) contends that more than 5 per cent of construction costs arise
519 from the rework due to tolerance issues. Forcada et al. (2016) estimate that tolerance issues are
520 among the most common and recurring defects in Spanish housing construction and make up
521 more than 9 per cent of the overall number of defects. Such problems can significantly affect
522 the quality of buildings, and their economic and functional lifecycle service (ACI 2014; Gibb
523 and Pavitt 2003; Milberg and Tommelein 2009; Talebi 2019). Despite the importance of
524 tolerances, their treatment in the literature is often limited to scattered and generic
525 recommendations about how to proactively avoid tolerance issues and improve tolerance
526 management. Arguably, a reason behind the none-existence of a holistic and widely accepted
527 solution to improve tolerance management could be the lack of an in-depth understanding of
528 the causes of tolerance issues (Milberg 2006; Talebi 2019). This is because solving a problem
529 first requires identifying its causes (Liker 2004).

530 The existing scattered attempts within academia to tackle specific causes of tolerance issues
531 found in each research work, rather than devising a solution to treat all of them, will not bring
532 about a panacea for tolerance management. Existing solutions devised to proactively prevent
533 these issues must be like putting together pieces of a puzzle, rather than creating isolated

534 solutions to remedy a number of specific causes. This is because all the identified causes bear
535 a responsibility for tolerance issues, as has been demonstrated through real-world examples in
536 this case study research. In particular, an effective solution for tolerance management should
537 put a major emphasis on the proactive identification of tolerance risks (Enshassi et al. 2019;
538 Shahtaheri et al. 2017) and then on planning to mitigate those tolerance risks (Talebi 2019).
539 The list of causes in this paper helps to develop a solution by which the identified risks and
540 their causes can be tackled and also provides insights to practitioners about potential tolerance
541 risks and their causes that need to be mitigated in projects. That is, knowing the causes will
542 improve the competency in the industry to deal with tolerance risks in a prescient manner,
543 which is a core principle of an effective tolerance management practice (Talebi et al. 2020a).
544 Therefore, this research is expected to provide a pivotal basis for developing a solution for
545 tolerance management whereby the identified causes can be tackled and a significant amount
546 of savings can be made.

547 **Conclusion**

548 The aim of this research was to identify potential causes of tolerance issues in construction.
549 The literature was used as a basis to create the preliminary list of causes. The case study
550 approach adopted in this research allowed to collect empirical data through direct observations
551 in two case projects, two group interviews, sixteen semi-structured interviews and document
552 reviews. Direct observations and group interviews were to identify examples of tolerance issues
553 in practice. Semi-structured interviews helped to collect rich data from which the experience
554 of participants about causes of the observed tolerance issues could be captured. In other words,
555 the semi-structured interviews were conducted to examine the causes of tolerance issues
556 encountered in real-world to avoid the subjectivity of reflecting the authors' or practitioners'
557 perceptions only. The document review was to corroborate evidence collected from the

558 interviews and it was also used for verifying information about the case projects that had been
559 presented in the interviews.

560 The findings from the literature and empirical studies were used to generate a list of eighteen
561 causes for the observed tolerance issues in the two case study projects. This list is also expected
562 to give an insight into causes behind the reoccurrence of tolerance issues in other projects
563 across the industry. Three causes not included in the prior body of knowledge on tolerance
564 management were found, namely ‘inconsistency between tolerance requirements of the project
565 and its budget’, ‘an incomplete project brief’, and ‘inferior types of construction methods’. The
566 identified causes from the literature were refined and verified by putting them in the context of
567 the observed tolerance issues. This was to verify that the identified causes have a practical basis
568 and also to refine those causes if necessary. In particular, the cause of ‘insufficient tolerance
569 information in specifications’ in the literature was further refined to ‘insufficient, inaccurate
570 and fragmented tolerance information in specifications’; the cause of ‘lack of tolerance
571 coordination during the project’ found in the literature was eliminated for the apter cause of
572 ‘poor communication of tolerance information’; the cause of ‘negligence of tolerances during
573 the tender process’ found in the literature was eliminated for the more descriptive cause of ‘the
574 lack of tolerance information in the project brief’; the causes of ‘ineffective quality control
575 documents’ and ‘inaccuracy of measurement devices’ were replaced with the more
576 comprehensive cause of ‘ineffective quality control process’.

577 This paper also consolidates scattered insights on causes of tolerance issues into a refined
578 and unified list of causes. The findings presented in this paper are expected to be a starting
579 point when identifying causes of tolerance issues and developing solutions for tolerance
580 management. Of note is that the construction industry is argued to lack a widely accepted
581 solution for tolerance management due to the lack of in-depth understanding of causes behind
582 the recurrence of tolerance issues.

583 Three limitations of this case study research should be explained. First, the empirical studies
584 revolve around commercial and industrial buildings and future research may find more causes
585 applicable to other types of construction projects. Second, this study was conducted in the UK
586 and may be affected by the special characteristics of the construction industry in this country.
587 However, it is arguable that these two limitations are partially mitigated as a result of reviewing
588 the literature on tolerance issues in various types of construction projects conducted in different
589 countries. Third, the causes identified for each tolerance issue were only inferred from the
590 accounts given by the interviewees, that is, other causes for each tolerance issue may be
591 conceivable. For example, a closer look at the tolerance issues and their causes reveals that
592 ‘ineffective quality control process’ and ‘poor workmanship’ could be attributed to tolerance
593 issue 8, ‘poor communication of tolerance information’ could be attributed to tolerance issue
594 10, and ‘insufficient, inaccurate and fragmented tolerance information in specifications’ could
595 be attributed to tolerance issue 11. It can be argued that this limitation arising from the
596 characteristics of the case study research was mitigated by sharing the potential causes of
597 tolerance issues identified from the literature with interviewees in order to increase their
598 awareness of the topic. Future research may attempt to undertake a similar study to find causes
599 of tolerance issues in other projects in order to generalise the causes, that is, developing a list
600 of causes without considering it in the context of a specific tolerance issue and project.

601 **Data Availability Statement**

602 Some or all data, models, or code that support the findings of this study are available from
603 the corresponding author upon reasonable request.

604 **References**

605 Abdul Nabi, M., and El-adaway, I. H. (2020). "Modular construction: Determining decision-
606 making factors and future research needs." *J. Manag. Eng.*, 36(6),
607 04020085.10.1061/(ASCE)ME.1943-5479.0000859

608 ACI (American Concrete Institute). (2014). *Guide for tolerance compatibility in concrete*
609 *construction (ACI 117.1R-14)*, ACI, Michigan, USA.

610 Alexander, S. (2014). *Design for movement in buildings*, Construction Industry Research and
611 Information Association, London, UK.

612 Alexander, S. J., and Lawson, R. M. (1981). *Design for movement in buildings*, Construction
613 Industry Research and Information Association, London.

614 Alshawi, M., and Underwood, J. (1996). "Improving the constructability of design solutions
615 through an integrated system." *Eng. Construct. Architect. Manag.*, 3(1/2), 47-
616 67.10.1108/eb021022

617 Arashpour, M., Heidarpour, A., Akbar Nezhad, A., Hosseinifard, Z., Chileshe, N., and
618 Hosseini, R. (2020). "Performance-based control of variability and tolerance in off-
619 site manufacture and assembly: optimization of penalty on poor production quality."
620 *Construct. Manag. Econ.*, 38(6), 502-514

621 Ballast, D. K. (2007). *Handbook of construction tolerances*, John Wiley & Sons, Inc., New
622 Jersey, USA.

623 BCSA (British Constructional Steelwork Association). (2010). *National structural steelwork*
624 *specification for building construction*, BCSA, London, UK.

625 Berg, J. v. d., and Holicky, M. (1989). *CIB W49 tolerances and FIG commission 6*
626 *engineering surveys*, CIB publication, Amsterdam, Netherlands.

627 Brinkmann, S. (2013). *Qualitative interviewing: Understanding qualitative research* Oxford
628 University Press, New York, USA.

629 Brookes, A. J. (2005). "Theory and practice of modular coordination." *the 13th Annual*
630 *Conference of the International Group for Lean Construction* Sydney.

631 BSI (British Standards Institution). (1994). *Structural use of steelwork in building: Code of*
632 *practice for design of composite slabs with profiled steel sheeting*, BSI, London, UK.

633 Chen, M., Feng, A., McAlinden, R., and Soibelman, L. (2020). "Photogrammetric point cloud
634 segmentation and object information extraction for creating virtual environments and
635 simulations." *J. Manag. Eng.*, 36(2).10.1061/(ASCE)ME.1943-5479.0000737

636 CONSTRUCT Concrete Structure Group. (2010). *National structural concrete specification*
637 *for building construction*, Maidenhead.

638 Davison, B., and Owens, G. W. (2012). *Steel designers' manual*, Blackwell Science, Ltd.,
639 Chennai, India.

640 Deming, W. E. (2000). *Out of the crisis*, The MIT Press, Cambridge.

641 Eisenhardt, K. M. (1989). "Building theories from case study research." *Acad. Manag. Rev.*,
642 14(4), 532-550.10.5465/AMR.1989.4308385

643 Enshassi, M. S., Walbridge, S., West, J. S., and Haas, C. T. (2019). "Integrated risk
644 management framework for tolerance-based mitigation strategy decision support in
645 modular construction projects." *J. Manag. Eng.*, 35(4), 05019004.05019004

646 Enshassi, M. S., Walbridge, S., West, J. S., and Haas, C. T. (2020). "Probabilistic risk
647 management framework for tolerance-related Issues in modularized projects: Local
648 and global perspectives." *J. Risk Uncertainty Eng. Syst. Part A: Civ. Eng.*, 6(1),
649 04019022.10.1061/AJRUA6.0001036

650 Fellows, R. F., and Liu, A. M. (2015). *Research methods for construction*, John Wiley &
651 Sons, Hong Kong.

652 Forcada, N., Macarulla, M., Gangoellis, M., and Casals, M. (2016). "Handover defects:
653 Comparison of construction and post-handover housing defects." *Build. Res. Inf.*,
654 44(3), 279-288.10.2307/30036550

655 Forsythe, P. (2006). "Consumer-perceived appearance tolerances in construction quality
656 management." *Eng. Construct. Architect. Manag.*, 13(3), 307-
657 318.10.1108/09699980610669714

658 Frank, G. C. (2012). *Construction quality: Do it right or pay the price*, Pearson Higher
659 Education, Inc., New Jersey, USA.

660 Gibb, A. G. F., and Pavitt, T. C. (2003). "Interface management within construction: In
661 particular, building facade." *J. Constr. Eng. M.*, 129(1), 8-15.10.1061/(ASCE)0733-
662 9364(2003)129:1(8)

663 Holbek, K., and Anderson, P. R. (1977). "European concepts of construction tolerances." *J.*
664 *Am. Concr. Inst.*, 74(3), 101-108

665 Jingmond, M., and Ågren, R. (2015). "Unravelling causes of defects in construction."
666 *Construct. Innovat.*, 15(2), 198-218.10.1108/CI-04-2014-0025

667 Jingmond, M., Ågren, R., and Landin, A. (2011). "Use of cognitive mapping in the diagnosis
668 of tolerance failure." *the 6th Nordic Conference on Construction Economics and*
669 *Organisation—Shaping the Construction/Society Nexus*Copenhagen.

670 Kagioglou, M., Cooper, R., and Aouad, G. (2001). "Performance management in
671 construction: a conceptual framework." *Construction management and economics*,
672 19(1), 85-95.10.1080/01446190010003425

673 Knight, A., and Ruddock, L. (2009). *Advanced research methods in the built environment*,
674 Wiley- Blackwell, Oxford, UK.

675 Landin, A. (2010). "Demands on the tolerances when industrialising the construction sector."
676 *New Perspective in Industrialisation in Construction*, G. Girmscheid, and F.
677 Scheublin, eds., International Council for Research and Innovation in Building and
678 Construction, Zurich, Switzerland, 197-205.

679 Landin, A., and Kämpe, P. (2007). "Industrializing the construction sector through
680 innovation–tolerance dilemma." *CIB World Congress*, CIB, Cape Town, South
681 Africa.

682 Lawson, M., Ogden, R., and Goodier, C. (2014). *Design in modular construction*, CRC Press,
683 Boca Raton, Florida.

684 Liker, J. K. (2004). *The Toyota way: 14 management principles from the world's greatest*
685 *manufacturer*, McGraw-Hill, New York, USA.

686 Love, P. E., Edwards, D. J., & Smith, J. (2016). Rework causation: Emergent theoretical
687 insights and implications for research. *J. Constr. Eng. M.*, 142(6), 04016010.
688 doi:10.1061/(ASCE)CO.1943-7862.0001114

689 Lu, Q., Parlikad, A. K., Woodall, P., Don Ranasinghe, G., Xie, X., Liang, Z., Konstantinou,
690 E., Heaton, J., and Schooling, J. (2020). "Developing a Digital Twin at building and
691 city levels: Case study of west Cambridge campus." *J. Manag. Eng.*, 36(3),
692 05020004.10.1061/(ASCE)ME.1943-5479.0000763

693 Meiling, J. H., Sandberg, M., and Johnsson, H. (2014). "A study of a plan-do-check-act
694 method used in less industrialized activities: Two cases from industrialized
695 housebuilding." *Construct. Manag. Econ.*, 32(1-2), 109-
696 125.10.1080/01446193.2013.812227

697 Milberg, C. (2006). "Application of tolerance management to civil systems." PhD dissertation
698 PhD dissertation.

699 Milberg, C., and Tommelein, I. D. (2009). "Tolerance and constructability of soldier piles in
700 slurry walls." *J. Perform. Constr. Facil.*, 24(2), 120-127.10.1061/(ASCE)CF.1943-
701 5509.0000079

702 Milberg, C., and Tommelein, I. D. (2009). "Tolerance and constructability of soldier piles in
703 slurry walls." *Journal of performance of constructed facilities*, 24(2), 120-
704 127.10.1061/(ASCE)CF.1943-5509.0000079

705 Milberg, C. T., and Tommelein, I. D. (2019). "Methods for managing tolerance compatibility:
706 windows in cast-in-place concrete." *J. Construct. Eng. Manag.*, 146(2),
707 04019105.10.1061/(ASCE)CO.1943-7862.0001728

708 O'Leary, Z. (2004). *The essential guide to doing research*, SAGE Publications, London.

709 Phares, B. M., Washer, G. A., Rolander, D. D., Graybeal, B. A., and Moore, M. (2004).
710 "Routine highway bridge inspection condition documentation accuracy and
711 reliability." *J. Bridge Eng.*, 9(4), 403-413.10.1061/(ASCE)1084-0702(2004)9:4(403)

712 Price, C., Goodier, C. I., Fouchal, F., and Fraser, N. (2019). "The role of standards in offsite
713 construction: A review of existing practice and future need." British Standards
714 Institute, London, UK.

715 Puri, N., Valero, E., Turkan, Y., and Bosché, F. (2018). "Assessment of compliance of
716 dimensional tolerances in concrete slabs using TLS data and the 2D continuous
717 wavelet transform." *Autom. Constr.*, 94, 62-72.10.1016/j.autcon.2018.06.004

718 Rahman, M. M. (2014). "Barriers of implementing modern methods of construction." *J.*
719 *Manag. Eng.*, 30(1), 69-77.10.1061/(ASCE)ME.1943-5479.0000173

720 Rausch, C., Edwards, C., and Haas, C. (2020). "Benchmarking and improving dimensional
721 quality on modular construction projects: A case study." *Int. J. Ind. Constr.*, 1(1), 2-
722 21.10.29173/ijic212

723 Rausch, C., Nahangi, M., Haas, C., and Liang, W. (2019). "Monte Carlo simulation for
724 tolerance analysis in prefabrication and offsite construction." *Autom. Construct.*, 103,
725 300-314.10.1016/j.autcon.2019.03.026

726 Rausch, C., Nahangi, M., Haas, C., and West, J. (2017). "Kinematics chain based
727 dimensional variation analysis of construction assemblies using building information
728 models and 3D point clouds." *Autom. Construct.*, 75, 33-
729 44.10.1016/j.autcon.2016.12.001

730 Rebolj, D., Pučko, Z., Babič, N. Č., Bizjak, M., and Mongus, D. (2017). "Point cloud quality
731 requirements for Scan-vs-BIM based automated construction progress monitoring."
732 *Automation in Construction*, 84(10.1016/j.autcon.2017.09.021), 323-334

733 Robson, C., and McCartan, K. (2015). "Real world research." Taylor & Francis, London, UK.

734 Rosenfeld, Y. (2013). "Root-cause analysis of construction-cost overruns." *Journal of*
735 *Construction Engineering and Management*, 140(1)

736 Safapour, E., and Kermanshachi, S. (2019). "Identifying early indicators of manageable
737 rework causes and selecting mitigating best practices for construction." *J. Manag.*
738 *Eng.*, 35(2), 04018060.10.1061/(ASCE)ME.1943-5479.0000669

739 Saunders, M., Lewis, P., and Thornhill, A. (2016). *Research methods for business students*,
740 Pearson Education, Harlow, UK.

741 Savoini, J.-J., and Lafhaj, Z. (2017). "Considering functional dimensioning in architectural
742 design." *Front. Architect. Res.*, 6(1), 89-95.10.1016/j.foar.2017.01.001

743 Seymour, D., Shammass-Toma, M., and Clark, L. (1997). "Limitations of the use of tolerances
744 for communicating design requirements to site." *Eng. Construct. Architect. Manag.*,
745 4(1), 3-22.10.1108/eb021037

746 Shahtaheri, Y., Rausch, C., West, J., Haas, C., and Nahangi, M. (2017). "Managing risk in
747 modular construction using dimensional and geometric tolerance strategies." *Autom.*
748 *Construct.*, 83.10.1016/j.autcon.2017.03.011

749 Shammass-Toma, M., Seymour, D. E., and Clark, L. (1996). "The effectiveness of formal
750 quality management systems in achieving the required cover in reinforced concrete."
751 *Construction Management and Economics*, 14(4), 353-
752 364.10.1080/014461996373421

753 Sun, W., and Gao, Y. (2018). "A Datum-Based model for Practicing Geometric
754 Dimensioning and Tolerancing." *Journal of Engineering Technology*, 35(2)

755 Talebi, S. (2019). "Improvement of dimensional tolerance management in construction." PhD
756 dissertation, University of Huddersfield, Huddersfield, UK.

757 Talebi, S., Koskela, L., Shelbourn, M., and Tzortzopoulos, P. (2016). "Critical review of
758 tolerance management in construction." *the 24th Annual Conference of the*
759 *International Group for Lean Construction* Boston, USA.

760 Talebi, S., koskela, L., Tzortzopoulos, P., and Kagioglou, M. (2020a). "Tolerance
761 management in construction: A conceptual framework." *Sustainability*,
762 12(3).10.3390/su12031039

763 Talebi, S., Koskela, L., Tzortzopoulos, P., Kagioglou, M., and Krulikowski, A. (2020b).
764 "Deploying Geometric Dimensioning and Tolerancing in Construction." *Buildings*,
765 10(4).<https://doi.org/10.3390/buildings10040062>

766 Talebi, S., Tzortzopoulos, P., Koskela, L., Poshdar, M., Tommelein, I. D., Tezel, A., and
767 Antunes, R. (2019). "A vision for the future of the computer-aided tolerance
768 management in construction based on the lessons learned from manufacturing." *CIB*
769 *World Building Congress* Hong Kong, China.

770 Taylor, S. J., Bogdan, R., and DeVault, M. (2015). *Introduction to qualitative research*
771 *methods: A guidebook and resource*, John Wiley & Sons, New Jersey, USA.

772 Tommelein, I., and Ballard, G. (2018). *Lean construction glossary*, Project Production
773 Systems Laboratory, UC Berkeley, California, USA.

774 Vorlíček, M., and Holický, M. (1989). *Analysis of dimensional accuracy of building*
775 *structures*, Elsevier, Amsterdam, Netherlands.

776 Ye, G., Jin, Z., Xia, B., and Skitmore, M. (2015). "Analyzing causes for reworks in
777 construction projects in China." *J. Manag. Eng.*, 31(6).10.1061/(ASCE)ME.1943-
778 5479.0000347

779 Yin, R. K. (2013). *Case study research: Design and methods*, SAGE Publications, California,
780 USA.

781

782

783

784

785

786

787

788

789

790

791

792

793

794

795

796

797 **Table 1**

No.	Identified Cause	Source															
		(Holbek and Anderson 1977)	(Berg and Holicky 1989)	(Alshawi and Underwood 1996)	((Shammas-Toma et al. 1996)	(Seymour et al. 1997)	(Milberg 2006)	(Ballast 2007)	(Alexander 2014)	(ACI 2014)	(Jingmond and Ågren 2015)	(Talebi et al. 2016)	(Rausch et al. 2017)	(Rausch et al. 2019)	(Milberg and Tommelein 2019)	(Enshassi et al. 2020)	(Talebi et al. 2020a)
1	Poor communication of tolerance information (e.g. lack of terminology)		•	•			•			•						•	•
2	Insufficient tolerance information in specifications		•				•		•							•	
3	Incompatibility between the specified tolerances and process capabilities						•					•	•				
4	Poor datum selection						•							•		•	
5	Unsuitable tolerance values in reference documents										•		•				
6	Negligence of tolerances during the tender process		•														
7	Inaccuracy of measurement devices									•		•					
8	Poor workmanship		•		•	•				•	•						
9	Lack of tolerance coordination during the project								•	•							
10	Lack of training on tolerance management						•							•			

11	Overreliance on reference documents to specify tolerances					•		•	•							•		•
12	Unforeseen behaviour of materials (i.e. unforeseen movement) and the lack of accurate guidance to anticipate the exact building movements								•									•
13	Ineffective quality control documents				•					•								
14	Neglecting the accumulation effects of deviations						•	•					•	•	•			
15	Lack of standard tolerances for all components in reference documents							•			•							
16	The lack of tolerances for interfacing components in reference documents	•															•	
17	Environmental conditions								•	•								
18	Unforeseen special causes									•								
19	Poor product design at connection points									•						•		

798

799 Table 2

800

Case Project	Description	Development Stage
A	A commercial building circa 7500 m ²	The building envelope and interior components were just to be installed.
B	A terraced warehouse circa 2.30 ha	The structural frame had been erected.

801

802 Table 3

Case Project	Corresponding No.	Description
A	Tolerance Issue 1	Depth of the concrete slabs
A	Tolerance Issue 2	Flatness of the concrete slabs
A	Tolerance Issue 3	Clash between the edge of the concrete slabs and cladding brackets
A	Tolerance Issue 4	Plumbness of the steel framing systems studs
A	Tolerance Issue 5	Clearance between the steelwork and the cladding
A	Tolerance Issue 6	Columns and cladding stone panels
A	Tolerance Issue 7	Columns and fins attached to the building envelope
B	Tolerance Issue 8	Structural frame and doorways
B	Tolerance Issue 10	Undulation of purlins
B	Tolerance Issue 11	Lack of fit in the steelwork

803

804 Table 4

Project A		Project B	
Interviewee	Interviewee Position	Interviewee	Interviewee Position
1	Project Director	10	Senior Engineer
2	Design Manager	11	Senior Surveyor
3	Architect	12	Planning Manager
4	Senior Planner	13	Envelope Package Manager
5	Quantity Surveyor	14	Senior Engineer
6	Quantity Surveyor	15	BIM Strategic Planner
7	Site Manager	16	Engineer of Concrete Subcontractor
8	Site Engineer		
9	Cladding subcontractor		

805

806 Table 5

807

No	Causes of Tolerance Issues (TIs) as Identified in the Literature and Empirically in Projects A and B	Literature	Empirical Studies										
			TI 1	TI 2	TI 3	TI 4	TI 5	TI 6	TI 7	TI 8	TI 9	TI 10	TI 11
1	Poor communication of tolerance information	•			•		•	•	•				
2	Incompatibility between the specified tolerances and process capabilities	•							•				
3	Poor datum selection	•								•			
4	Inconsistency between tolerance requirements of the project and its budget		•					•		•		•	
5	Insufficient, inaccurate and fragmented tolerance information in specifications	•			•			•	•	•	•		
6	An incomplete project brief		•										
7	Neglecting the accumulation effects of deviations	•										•	
8	Overreliance on reference documents to specify tolerances	•	•		•								
9	The lack of accurate guidance to anticipate the exact building movements	•					•	•					
10	Ineffective quality control process	•				•							•
11	Inferior types of construction methods		•									•	
12	Poor workmanship	•				•					•	•	
13	Poor product design at connection points	•							•				
14	Lack of training on tolerance management	•								•			
15	The lack of tolerances for interfacing components in reference documents	•			•								
16	The lack of standard tolerances for all components in reference documents	•											
17	Environmental conditions	•	•	•									
18	Unforeseen special causes	•	•	•									

808

809


810

811



812


813 Figure 1



814


815 Figure 2

816



817

818 Figure 3




819

820 Figure 4



821

822 Figure 5



823

824

825

826 Figure 6

827

828

829

830

831

832



833

834 Figure 7



835

836 Figure 8

837

838

Fig. 9 Lack of fit of the beam between two grid lines

